

Visual Discrepancies

Customer:	Sample Facility	Date 9/1/2008	Survey 3
-----------	------------------------	-------------------------	--------------------

Discrepancy		
Item Inspected	Location	Equipment ID
Main Distribution Panel (1 HTR CP)	Main Electric Room	
Problem Description	Problem Solution	
Insulation is damaged.	Replace wire.	
Digital Camera Image		

