

Visual Discrepancies

Customer:	Sample Facility	Date 9/1/2008	Survey 5
-----------	------------------------	-------------------------	--------------------

Discrepancy	
Item Inspected	Location
Siemens 300KVA Transformer	Main Electric Room
Problem Description	Problem Solution
Connections and wiring are burnt on the south enclosure heater.	De-energize and replace parts.

Digital Camera Image

